

GUIDELINE FOR QUALITY TEST

IMPLEMENT THE WEIGHT AND THICKNESS TEST
THEN COMPARE WITH THE PARAMETER SHOWN
ON THE PRINTING ON THE SURFACE OF THE STEEL SHEET.



PALMER

Measure the thickness at 3 different spots on the steel sheet, then compare the average of the results with the announced thickness.



WEIGHT

Compare the actual weight with the invoicing weight on the documents, sales contract